



**MASTER COPY**


DO NOT REMOVE FROM FILE  
AMENDMENT DATES

ISSUE No.

FILE DATE


REPRINT  
ORDERED

# Transarc Tradesman Parts List (240V Version)



Item	Description	Part No.
1	Potentiometer	1409732
-	Knob for item 1	1406122
2	Transformer	1409800
3	Choke	1409801
4	Thyristor	1409700

Item	Description	Part No.
5	Printed Circuit Board	1409803
6	Fan Assembly	1409178
7	Thermostat	1409730
8	Welding Sockets	1404314

Item	Description	Part No.
-	Welding plugs (for item 8)	1404315
-	Varistor	1409747
-	Primary Cable	1409808

*ADDITIONAL THERMOSTAT ADDED FROM 3C ONWARDS*

**OPTIONAL EXTRAS**

**ORDERING INFORMATION**

- Scratch Start TIG Kit for Transarc DC 130 Pt.No. 1407736 comprising:
- Power Connector Assembly Pt.No. 1407737
  - Gas Hose Pt.No. 606503
  - Argon Regulator AR-2 Pt.No. 1254241
  - Flowmeter Pt.No. 603457
  - TG 100 TIG Torch with Valve Pt.No. 1408260
  - TG 100 Accessory Kit Pt.No. 1408020
  - TIG Welders Accessory Kit Pt.No. 1407716

- Transarc DC 130/240V Package Pt.No. 1407723 comprising:
- Transarc DC 130 with Primary Cable  
Accessory Kit for Manual Metal Arc Welding  
Pt.No. 1407721 consisting of:-
- Welding Lead and Electrode Holder 25mm Dinse
  - Work Return Lead and Clamp 25mm Dinse
  - Hand Shield with Glasses
  - Chipping Hammer
  - Wire Brush

**Note:**

Transarc Tradesman 110V version is available, Please quote Pt.No. 1410360